

AMENDMENTS TO THE SPECIFICATION:

Please replace the last paragraph on page five of the specification as follows:

The hollow screw has numerous holes 17 for letting air out. The air passes further through the slits in the roll into the processing zone 6, and helps to separate shell parts, etc. from the wheat grains. The air is pressed into the hollow screw by means of a fan.